

INSTRUCTIONS Safety Recall Disclosure Form

INSTRUCTIONS for Completing the Pennsylvania Act 59 of 2018 Safety Recall Disclosure Form:

Copy and Paste the recall results from www.safercar.gov which leads to <https://www.nhtsa.gov/recalls> VIN search into this form. Then print and provide to the Retail Customer *at the time of vehicle purchase*. Here are explanatory screenshots and a sample VIN search and result to COPY and PASTE into the form:



Safety Issues & **Recalls**

VIN VEHICLE CAR SEATS TIRES EQUIPMENT

Vehicle Identification Number (VIN)

Every vehicle has a unique VIN. Enter a VIN to learn if a specific vehicle needs to be repaired as part of a recall.

Enter 17 Character VIN 0/17 

Safety Issues & **Recalls**

VIN VEHICLE CAR SEATS TIRES EQUIPMENT

Vehicle Identification Number (VIN)

Every vehicle has a unique VIN. Enter a VIN to learn if a specific vehicle needs to be repaired as part of a recall.

2D4GP74L93R232052 17/17 

Sample VIN.

SAMPLE FORM

Safety Recall Disclosure Form for Retail Vehicle Sales at Pennsylvania Dealerships

1. Recall VIN Search Results:

(COPY and PASTE Safety Recall Results here (from VIN Search at www.safercar.gov which leads to <https://www.nhtsa.gov/recalls> where the VIN search is input to obtain the safety recall VIN search results.)

2D4GP74L93R232052

<https://www.nhtsa.gov/recalls>

The screenshot shows the NHTSA VIN search results for the VIN 2D4GP74L93R232052. The page title is "Vehicle Identification Number (VIN)" and it includes a search bar with the VIN and a search icon. Below the search bar, the vehicle is identified as a "2003 DODGE GRAND CARAVAN". The recall information is as follows:

- 1 Recalls** associated with this VIN
- Aug 03, 2004**
- Manufacturer Recall Number:** D37
- NHTSA Recall Number:** 04V-386
- Recall Status:** Recall Incomplete
- Summary:** ON CERTAIN MINIVANS EQUIPPED WITH 3.3 OR 3.8L V-6 ENGINE, THE UPPER POWER STEERING COOLER HOSE MAY SPLIT AND CAUSE A FLUID LEAK.
- Safety Risk:** POWER STEERING FLUID LEAKAGE IN THE PRESENCE OF AN IGNITION SOURCE CAN RESULT IN AN UNDER HOOD FIRE.
- Remedy:** DEALERS WILL REPLACE THE UPPER POWER STEERING COOLER HOSE
- Manufacturer's Notes:** For more information, visit recalls.mopar.com or call 1-800-853-1403. Please have your VIN ready when calling.

2. Additional Information about Safety Recalls:

Find a dealer.

Locate a dealer near you to get your vehicle repaired.

<https://www.mopar.com/en-us/services/find-dealer.html>

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an online complaint with NHTSA.

Where's my VIN?

Look on the lower left of your car's windshield for your 17-character Vehicle Identification Number. Your VIN is also located on your car's registration card, and it may be shown on your insurance card.



What this <https://www.safercar.gov/> which leads to <https://www.nhtsa.gov/recalls> VIN search tool covers:

- Vehicle safety recalls that are incomplete
- Vehicle safety recalls conducted over the past 15 calendar years
- Vehicle safety recalls conducted by major light auto automakers, including motorcycle manufacturers.

What this <https://www.safercar.gov/> which leads to <https://www.nhtsa.gov/recalls> VIN search tool does not cover:

- Completed safety recall information
- Manufacturer customer service or other nonsafety recall campaign
- International vehicles
- Very recently announced safety recalls for which not all VINs have been identified
- Safety recalls that are more than 15 years old (except where a manufacturer offers more coverage)
- Safety recalls conducted by small vehicle manufacturers, including some ultra-luxury brands and specialty applications.

For more information about safety recalls, you can go to <https://www.safercar.gov/> and <https://www.nhtsa.gov/recalls>.

FORM: Safety Disclosure Form for PA Act 59 of 2018